


Proper picture layout of a properly cleaned grease duct, 2nd picture is the hood at start of job.



Need overview pictures of fan and roof area before and after cleaning



Next is the back of the fan blades. You will need a camera set at close up for this inspection.



Looking into the top of a upblast style fan.



fan intake




Looking down a vertical stack from the roof




Above a hood looking at a horizontal duct and access plates




Looking into a longer horizontal(notice the additional ductwork beyond the curve and another inspection plate).




Looking into a horizontal above A hood drop-(notice the additional ductwork beyond the curve).




Looking inside a typical horizontal plenum for a "T" system above the hood.




Looking up from the hood into the grease duct



Looking up from the hood into the grease duct, partially inspecting the horizontal plenum area



Looking up a vertical without a horizontal(notice fan intake at top of duct)



Looking behind the filter rack



Looking into the grease troughs in the hood area